

Vitals Desktop Release Notes.

Vitals Desktop 3.0.2

Added Query feature (List and New)
Added Desktop and Mobile Help file display
Added Up/Down field move to Custom Data screen
Added Update Query to query options
Help files in PDF format, New 3.0.2 PDF Files. Fixed Delete query for Update queries.

Vitals Desktop 3.0.4

Fixed International report dates and cleared out Database template
Prompt for company name on new database
International date support on activity report
Removed choices table from template

Vitals Desktop 3.0.5

New Database Template.
Added Reset prompt to Sync Silver

Vitals Desktop 3.0.6

Added On error code for Datalogger port selection.
Fixed Filter Program Exception

Vitals Desktop 3.0.7

Added TransferID to Mobile Transfer.
Added count of activities to Data Transfer screen.
Add View list of transfered Activities for New Database.
New Expandable Main Menu Screen
New Follow-up Tab Added to main menu
Initial New Remarks screen
New Remarks Database editor
Added Queues to Test Database
Data Transfers now reset the yellow box.

Vitals Desktop 3.1.0

Fixed C:\(Root) Write Problem during Activities Report
Update database creates query AvgLatLon
Export GPS changed to use average lat/long from Activities table.
Added new Detail Report for current selected valves or activities.
Added Lock Valves Feature to Desktop software
Display total count of Activities
Added Scroll bar to Valve/Activities edit window.

Vitals Desktop 3.1.1

Included in the System_SR_ENU_wm.cab in install and program file directory.

Vitals Desktop 3.1.3

Multi torque chart save function. It is now possible to highlight and save torque chart to disc/directory of your choice and save as Bit map, JPEG or text data file for all selected activities torque charts under Browse Activities function of Vitals desktop.

Vitals Mobile Release Notes.

Vitals Mobile 3.0.2

Type 1 & 2 machines increased to 75 foot pounds torque

Vitals Mobile 3.0.5

Changed Transducer Error Parameters to prevent Torque exceeding limit

Vitals Mobile 3.0.6

Upgraded for Nomad which apparently has a different screen resolution that causes Fix Bad Com Port error message.

Stretch the Vitals Logo.

Placed Main Screen under GPS Controller Component.

Fix torque random number to 15. Corrected warning message.

Vitals Mobile 3.0.7

Added ability to lock settings screen from update.

Added controller button and menu button no main screen.

Added GPS Baud Rate setting.

Changed random number again.

Vitals Mobile 3.0.8

Changed and Added a random number to torque again.

Vitals Mobile 3.0.9

Disabled GetStrings look-up

Vitals Mobile 3.1.0

Added Lock Valves Feature to Mobile unit.

Vitals Mobile 3.1.2

Disabled GetStrings look-up again (CVS Tip)